







Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
RIVELIN VALLEY ROAD	O/s 25-27	Decay	Decay	Tilia x europea	Plant in new 800mm pit o/s 25-27 (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Next to pedestrian crossing from Walkley Bank Plantation	Structural	Structural Integrity	Tilia x europea	Plant in new 800mm pit next to pedestrian crossing, (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road - see map, adjacent driveway for convent	dead	Dead	Fraxinus excelsior	Plant in adjacent clear suitable space in verge on Rivelin Valley Road	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road - see map, adjacent Convent driveway	dead	Dead	Fraxinus excelsior	in opposite footway nr. paddling pool entrance	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road - see map, just beyond driveway to convent	Structural	Structural Integrity	Fraxinus excelsior	Plant in verge opp Hagg hill junction.	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road - at end of driveway for convent	Structural	Structural Integrity	Fraxinus excelsior	Plant in verge at end of convent driveway	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road - see map	Structural	Structural Integrity	Salix caprea	5m W of original location - see map	Tilia x europea
RIVELIN VALLEY ROAD	Revelin Valley Road - see map	Structural	Structural Integrity	Tilia x europea	same location - see map	Tilia x europea
RIVELIN VALLEY ROAD	Revelin Valley Road - see map	Dead	Dead	Tilia x europea	same location - see map	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road - see map	Structural	Structural Integrity	Tilia x europea	same location - see map	Tilia x europea
RIVELIN VALLEY ROAD	Facing/opp 19	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit opposite 19 (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	O/s 21-23	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit o/s 21-23 (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	O/s 29-31	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit o/s 29-31 (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Opposite 31	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit opp 31 (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road opposite 35-37	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit opp 39 (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Opposite 43	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit opp 43 (same as felled tree)	Tilia x europea

RIVELIN VALLEY ROAD	10m southward from lime opposite 43, ie next one in the avenue	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit adjacent to mature tree and other newly planted limes (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit equidistant between mature trees either side (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit equidistant between mature trees either side (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit equidistant between mature trees either side (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit equidistant between mature trees either side (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit equidistant between mature trees either side (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit equidistant between mature trees either side (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit equidistant between mature trees either side (same as felled tree)	Tilia x europea

RIVELIN VALLEY ROAD	Rivelin Valley Road	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit equidistant between mature trees either side (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit equidistant between mature trees either side (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit equidistant between mature trees either side (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit equidistant between mature trees either side (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit equidistant between mature trees either side (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	Rivelin Valley Road	Damage to Surface	Damage to Surface	Tilia x europea	Plant in new 800mm pit equidistant between mature trees either side (same as felled tree)	Tilia x europea
RIVELIN VALLEY ROAD	O/s 11a	Dangerous	Significant scaffold limb cavity (TR: Felling-)	Tilia x europea	outside 11a in tree pit	
RIVELIN VALLEY ROAD	Rivelin Valley Road	Dying	dead - dying (TR: Felling-)	Tilia x europea	next to crossing in original location	
RIVELIN VALLEY ROAD	Rivelin Valley Road	Dying	dead/dying. (TR: Felling-)	Tilia x europea	10m north of the crossing in original location	
RIVELIN VALLEY ROAD	Rivelin Valley Road	Dangerous	Significant Cavity	Tilia x europea	Opposite 11a	
RIVELIN VALLEY ROAD	see map	Dead	Tree missing on inspection	Tilia cordata X mongolica	Rivelin valley road, Between acer and oak, verge see map	

Rivelin Valley Road		Damage	Damage to Surface	Tilia x europea	Plant in new 800mm pit equidistant between mature trees either side (same as felled tree)	Tilia x europea
---------------------	--	--------	-------------------	-----------------	-------------------------------------------------------------------------------------------------------	-----------------